

District 1

1625 N. French Dr., Hobbs, NM 88249
Phone (505) 393-6161 Fax (505) 393-0122

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-33329
Property Name Central Vacuum Unit	Well No 186

Surface Location

UL - Lot M2A 31	Section 31	Township 17S	Range 35E	Feet from 607	N/S Line S	Feet From 2630	E/W Line E	County LEA
--------------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 3-28-2019
--	--	---	--	-------------------

OBSERVED DATA

	(A)Surf-Intern	(B)Intern(1)	(C)Intern(2)	(D)Prod Csm	(E) tubing
Pressure	0			0	150
Flow Characteristics					
Puff	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	CO2 _____
Steady Flow	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	WIR _____
Surges	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	GAS _____
Down to nothing	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	If applicable type
Gas or Oil	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	fluid injected for
Water	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Chris Lopez</i>	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test <i>[Signature]</i>
E-mail Address	
Date:	Phone
Witness <i>Ray Roberts</i>	