

District I

1625 N French Dr., Hobbs, NM 88246
Phone (575) 393-6161 Fax (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-38641
Property Name Central Vacuum Unit	Well No. 459

1. Surface Location

UL - Lot D	Section 31	Township 17S	Range 35E	Feet from 1050	N/S Line N	Feet From 566	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 3-20-18
--	--	--	---	-----------------

OBSERVED DATA



	(A) Surf-Interm	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	0	n/a	n/a	0	1741
Flow Characteristics					
Puff	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	CO2 _____
Steady Flow	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	WTR _____
Surges	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	GAS _____
Down to nothing	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	If applicable type
Gas or Oil	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	fluid injected for
Water	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD

APR 24 2019

RECEIVED

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	
Phone:	
Witness: 