

Hobbs1625 N. French Dr. Hobbs, NM 88241
Phone: (505) 493-6266 Fax: (505) 493-6720State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	AD Number 30-025-440461
Property Name Central Vacuum Unit	Well No 249

7. Surface Location

U.T. - Lot 6	Section 31	Township 17S	Range 36E	Feet from 109	N/S Line N	Feet from 1414	E/W Line W	County Lea
-----------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ SWD	PRODUCER ☒ OIL GAS	DATE 3-28-2019
--	--	---------------------	--	-------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		120	125
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 _____
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR _____
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS _____
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	If applicable type _____
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Fluid injected for _____
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RHDMS
Title:	Re-test 
E-mail Address:	
Date:	Phone
Witness 