

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HC-25 OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Chevron Midcontinent, LP		Operator Name	API Number
Property Name		Well No	
Central Vacuum Unit		274	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
E	31	17S	35E	2033	N	1187	W	Lea



Well Status

TAD Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO	YES ☒ NO	☒ SWD	OIL GAS	4-12-19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Fishing
Pressure	☒	☒		☒	
Flow Characteristics					
Puff	☒ Y/N	☒ Y/N	☒ Y/N	☒ Y/N	CO2 _____
Steady Flow	☒ Y/N	☒ Y/N	☒ Y/N	☒ Y/N	WTR _____
Surges	☒ Y/N	☒ Y/N	☒ Y/N	☒ Y/N	GAS _____
Down to nothing	☒ Y/N	☒ Y/N	☒ Y/N	☒ Y/N	If applicable type
Gas or Oil	☒ Y/N	☒ Y/N	☒ Y/N	☒ Y/N	fluid injected for
Water	☒ Y/N	☒ Y/N	☒ Y/N	☒ Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title:		Re-test 	
E-mail Address			
Date:	Phone		
	Witness		