

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Chevron Midcontinent, LP		Operator Name	30-025-26732
Property Name		Well No	302
Central Vacuum Unit			

Surface Location

PL - Lat	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
D	6	18 S	35 E	170	N	330	W	LEA

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO	YES ☒ NO	INJ SWD	OIL GAS	3-28-2019

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Case	(E) Tubing
Pressure	0	0	0	115	200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title:		Re-test	
E-mail Address			
Date:	Phone:		
	Witness: 		