

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
STATE COUNTY
APR 24 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-26786
Property Name Central Vacuum Unit	Well No 142

Surface Location

U.L. - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
I	6	183	35E	1680	S	330	E	LEE

Well Status

TA'D Well <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	SHUT-IN <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	INJECTOR <input checked="" type="checkbox"/> N/A <input type="checkbox"/> SWD	PRODUCER <input type="checkbox"/> OIL <input type="checkbox"/> GAS	DATE 3/19/19
--	--	--	---	-----------------

OBSERVED DATA

	(A) Surf-Intern	(B) Intern(1)	(C) Intern(2)	(D) Prod Case	(E) Tubing
Pressure	0	0	0	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	N/N	N/N	N/N	N/N	If applicable type _____
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for _____
Water	Y/N	Y/N	Y/N	Y/N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Chris Fero</i>	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS <i>[Signature]</i>
Title:	Re-test
E-mail Address	
Date:	Witness: <i>May Robinson</i>