

HOBBS OCD

APR 24 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-32807
Property Name Central Vacuum Unit		Well No 203

Surface Location

1/4 - Lot F	Section 6	Township 18 S	Range 35 E	Feet from 1913	N/S Line N	Feet From 2476	E/W Line W	County LEA
----------------	--------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 3-28-2019
------------------	----------------	-----------------	-----------------	-------------------

OBSERVED DATA

	(A)Surf Inter	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Fubing
Pressure	0			120	150
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dan Rogers		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness: 