

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-045-03077
Property Name Central Vacuum Unit	Well No 105

7. Surface Location

U.L. - Lot E	Section 6	Township 18 S	Range 35 E	Feet from 1980	N/S Line N	Feet from 484	E/W Line W	County LEA
-----------------	--------------	------------------	---------------	-------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 3-28-2019
--	--	---	--	-------------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		110	200
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	CO2 _____
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	WTR _____
Surges	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	GAS _____
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	If applicable type _____
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	Fluid injected for _____
Water	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Chris Lopez</i>	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test <i>[Signature]</i>
E-mail Address	
Date:	Phone
Witness <i>[Signature]</i>	