

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

|                                           |  |                            |
|-------------------------------------------|--|----------------------------|
| Operator Name<br>Chevron Midcontinent, LP |  | API Number<br>30-025-22451 |
| Property Name<br>Central Vacuum Unit      |  | Well No.<br>118            |

Surface Location

|                |              |                  |               |                  |               |                   |               |               |
|----------------|--------------|------------------|---------------|------------------|---------------|-------------------|---------------|---------------|
| N/L - Lot<br>N | Section<br>6 | Township<br>18 S | Range<br>35 E | Feet from<br>990 | N/S Line<br>S | Feet From<br>1650 | E/W Line<br>W | County<br>LEA |
|----------------|--------------|------------------|---------------|------------------|---------------|-------------------|---------------|---------------|

Well Status

|                  |                |                 |                 |                   |
|------------------|----------------|-----------------|-----------------|-------------------|
| TA'D Well<br>YES | SHUT-IN<br>YES | INJECTOR<br>INJ | PRODUCER<br>OIL | DATE<br>3-28-2019 |
|------------------|----------------|-----------------|-----------------|-------------------|

OBSERVED DATA

|                      | (A) Surf-Interm | (B) Interm (1) | (C) Interm (2) | (D) Prod Casing | (E) Tubing         |
|----------------------|-----------------|----------------|----------------|-----------------|--------------------|
| Pressure             | 0               |                |                | 115             | 400                |
| Flow Characteristics |                 |                |                |                 |                    |
| Puff                 | Y/N             | Y/N            | Y/N            | Y/N             | CO2                |
| Steady Flow          | Y/N             | Y/N            | Y/N            | Y/N             | WIR                |
| Surges               | Y/N             | Y/N            | Y/N            | Y/N             | GAS                |
| Down to nothing      | Y/N             | Y/N            | Y/N            | Y/N             | If applicable type |
| Gas or Oil           | Y/N             | Y/N            | Y/N            | Y/N             | fluid injected for |
| Water                | Y/N             | Y/N            | Y/N            | Y/N             | Waterflood         |

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

|                 |        |                           |
|-----------------|--------|---------------------------|
| Signature:      |        | OIL CONSERVATION DIVISION |
| Printed name:   |        | Entered into RBDMS        |
| Title:          |        | Re-test                   |
| E-mail Address: |        |                           |
| Date:           | Phone: |                           |
| Witness:        |        |                           |