

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-25796
Property Name Central Vacuum Unit	Well No 106

Surface Location

PL - Lat E	Section 6	Township 18S	Range 35E	Feet from 2520	NS Line N	Feet From 1040	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	-------------------	--------------	-------------------	---------------	---------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 3/19/19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	0	1572
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Chris Pers</i>	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone
Witness <i>Greg Johnson</i>	