

District I
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-6120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-25797
Property Name Central Vacuum Unit	Well No 108

Surface Location

UL - Lat 6	Section 6	Township 18S	Range 35E	Feet from 2630	N/S Line N	Feet From 1480	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status


TA'D Well YES	SHUT-IN YES	INJECTOR IN	PRODUCER OIL	DATE 3/19/19
------------------	----------------	----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1822
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. csg. had slight water - blew to zero

Signature: 	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test
E-mail Address	
Date:	
Phone	
Witness: Gary Palmer	