

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	Well No. 113
Property Name Central Vacuum Unit	

2. Surface Location

UL - Lot L	Section 6	Township 18S	Range 35E	Feet from 1620	N/S Line S	Feet From 1100	E/W Line W	County LTC
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ IN ☐ SWD	PRODUCER OIL ☐ GAS	DATE 3/19/19
--	--	---	---	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1811
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	CO2 _____
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	WTR _____
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	GAS _____
Down to nothing	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	If applicable type
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	fluid injected for
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Mary F. Lopez	Entered into RBDMS 
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: 	