

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
APR 24 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-25799
Property Name Central Vacuum Unit		Well No 114

Surface Location

UL - Lot K	Section 6	Township 18S	Range 35E	Feet from 1960	N/S Line S	Feet From 2100	EAV Line W	County LCC
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR YES	PRODUCER OIL	DATE 3/19/19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Intern(1)	(C)Intern(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1304
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test 
E-mail Address:		
Date:	Phone:	
Witness: 