

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-25802
Property Name Central Vacuum Unit	Well No 121

2. Surface Location

U/L - Lq N	Section 6	Township 18S	Range 35E	Feet from 1001	N/S Line S	Feet From 2380	E/W Line W	County Log
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR (INJ)	PRODUCER OIL	GAS	DATE 3/19/19
------------------	----------------	-------------------	-----------------	-----	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	183
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address	
Date:	
Phone	
Witness Ray Robinson	