

HOBBS OCD

APR 24 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 03-025-25994
Property Name Central Vacuum Unit		Well No 133

Surface Location

U/L - Lat B	Section 17	Township 18S	Range 31E	Feet from 10	N/S Line N	Feet From 1550	E/W Line E	County Lee
----------------	---------------	-----------------	--------------	-----------------	---------------	-------------------	---------------	---------------

Well Status


TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 3/19/19
------------------	----------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	908
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

St prod. csg. had slight water- blew to zero

Signature: 		OIL CONSERVATION DIVISION
Printed name		Entered into RBDMS
Title:		Re-test
E-mail Address		
Date:	Phone	
	Witness 