

HOBBS OCD

APR 24 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-26787
Property Name Central Vacuum Unit		Well No 143

Surface Location

U/L - Lat	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
-----------	---------	----------	-------	--	-----------	----------	-----------	----------	--------

Well Status


TA'D Well	SHUT-IN	INSPECTOR	PRODUCER	DATE
YES NO	YES NO	INJ SWD	OIL GAS	4-12-19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Casing
Pressure	0	0	N/A	0	1244
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WER
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Had ~~pressure~~ on casing, Bled down
pressure

Signature: 		OIL CONSERVATION DIVISION
Printed name		Entered into RBDMS
Title:		Re-test 
E-mail Address:		
Date:	Phone:	
	Witness	