

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-41345
Property Name Central Vacuum Unit	Well No 218

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
M	6	18 S	35 E	942	S	1015	W	LEP



Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	INJ ☐ SWD ☐	OIL ☒ GAS ☐	3-28-2019

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		109	100
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	CO2 _____
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	WTR _____
Surges	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	GAS _____
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	If applicable type
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	fluid injected for
Water	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☐	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	Phone:
Witness: 