

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name

HOBBS OCD

API Number

ConocoPhillips Company

APR 24 2019

3002502916

Well Name

RECEIVED

Well No

East Vacuum GB-SA 2864

013

BEE

Surface Location

UL - Lot	SEC	Tnsp	Range	Feet From	N/S Line	Feet From	E/W Line	County
D	28	17S	35E	660	N	660	W	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO	YES ☒ NO	INJ ☐ SWD ☒	GAS ☐	4-4-19

OBSERVED DATA

	(A)Surface	(B)Interm (1)	(C)Interm (2)	(D) Prod Csg	(E)Tubing
Pressure	0	NA	NA	20	50
Flow Characteristics					CO2
Puff	Y / ☒ N	Y / N	Y / N	Y / N	WTR
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / N	GAS
Surges	Y / ☒ N	Y / N	Y / N	Y / N	
Down to Nothing	☒ Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	
Water	Y / ☒ N	Y / N	Y / N	Y / N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.

None

Signature: Cesar Sigala	OIL CONSERVATION DIVISION
Print name: Cesar Sigala	Entered in RBDMS
Title: MSO	Re-test
E-mail Address: Cesar.Sigala@contractor.conocophillips	
Date: 4-4-19	Phone: 575-659-9053
Witness:	