

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
APR 26 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name SUN DOWN ENERGY LP	API Number 30-025-28905
Property Name Kochia STATE	Well No. 1

Surface Location									
UL - Lot 0	Section 35	Township 1S-S	Range 36E		Feet from 990	N/S Line S	Feet From 2310	E/W Line E	County Lea

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 4-16-19	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Q-C	Q		Q	VAC
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Belinda Bradley	OIL CONSERVATION DIVISION
Printed name: Belinda Bradley	Entered into RBDMS
Title: Field Production Analyst	Re-test
E-mail Address: bbradley@sundownenergy.com	212
Date: 4-16-19	
Phone:	
Witness: Rick Rickman	

INSTRUCTIONS ON BACK OF THIS FORM