

HOBBS OCD

APR 29 2019

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-24333
Property Name Vacuum Grayburg San Andres Unit		Well No 005

7 Surface Location

UL - Lat N	Section 1	Township 18S	Range 34E	Feet from 210	N/S Line S	Feet From 1420	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES ☒	SHUT-IN YES ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 4-14-19
---	---	--	--	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interam(1)	(C) Interam(2)	(D) Prod Cmg	(E) Tubing
Pressure	0	N/A	N/A	0	1116
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☒ N	☐ Y ☒ N	☒ Y ☐ N	CO2 ☐
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	WTR ☒
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☐ N	☐ Y ☒ N	☐ Y ☒ N	☒ Y ☐ N	If applicable type
Gas or (oil)	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	fluid injected for
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION
Printed name		Entered into RBDMS
Title:		Re-test 
E-mail Address		
Date:	Phone	
	Witness	