

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

HOBBS OCO

APR 29 2019

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		RECEIVED 30-023-36683
Property Name Vacuum Grayburg San Andres Unit		
Well No. 132		

* Surface Location

U. - Lot 1	Section 2	Township 18S	Range 34E	Feet from 2630	N/S Line S	Feet from 660	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------



Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR (INJ)	PRODUCER OIL	DATE 4-14-19
------------------	----------------	-------------------	-----------------	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	1792
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness:		