

HOBBS 000

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 29 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-40999
Property Name Vacuum Grayburg San Andres Unit		Well No 247

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
H	2	18 S	34 E	1800	N	145	E	Lea



Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 4-14-19
--	--	--	---	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	1790
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test 	
E-mail Address:			
Date:	Phone:		
Witness:			