

District I
1625 N. French Dr. Hobbs NM 88240
Phone (575) 391-6161 Fax (575) 391-0720

HOBBS OCO

APR 29 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-01267
Property Name Vacuum Grayburg San Andres Unit		Well No 052

Surface Location

CL - Lat	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	2	18S	34E	660	N	1980	W	Lea

Well Status

TA'D Well ☒ YES ☐ NO	SHUT-IN ☐ YES ☐ NO	INJECTOR ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 4/13/19
--	---	---	--	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure	0	AVA	AVA	50	9
Flow Characteristics					
Pull	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	CO2 _____
Steady Flow	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	WTR _____
Surges	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	GAS _____
Down to nothing	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	If applicable type _____
Gas or Oil	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	fluid injected for _____
Water	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title:		Re-test	
E-mail Address			
Date:	Phone		
	Witness		