

District I
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 391-6161 Fax (575) 393-0720

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 29 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name	API Number
Chevron Midcontinent, LP	30-025-02271
Property Name	Well No
Vacuum Grayburg San Andres Unit	024H

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
1	2	18S	34E	1980	S	660	E	Lea



Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	INJ ☐ SWD ☐	☒ OIL ☐ GAS	4/13/19

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	1	NA	NA	100	200
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	CO2 ☐
Steady Flow	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	WTR ☐
Surges	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	GAS ☐
Down to nothing	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	If applicable type
Gas or Oil	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	fluid injected for
Water	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	
Phone	
Witness	