

HC000000

APR 29 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-31993
Property Name Vacuum Grayburg San Andres Unit		Well No. 227

Surface Location

UL - Lot J	Section 1	Township 18 S	Range 34 E	Feet from 1980	N/S Line S	Feet from 1755	E/W Line E	County Lea
---------------	--------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

T&D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 4/13/19
-----------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	120	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type _____
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for _____
Water	Y/N	Y/N	Y/N	Y/N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title:		Re-test	
E-mail Address			
Date:	Phone:		
	Witness:		