

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 29 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP		API Number 30-025-02272
Property Name Vacuum Grayburg San Andres Unit		Well No. 023

Surface Location

U.L. - Lot J	Section 2	Township 18S	Range 34E	Feet from 1980	N/S Line S	Feet from 1980	E/W Line E	County Lea
-----------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR INJ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 4/14/19
--	--	---------------------	--	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	50	0
Flow Characteristics					
Puff	2 N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type _____
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Fluid injected for _____
Water	Y / N	Y / N	Y / N	Y / N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address			
Date:	Phone		
	Witness		