

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD

APR 29 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-24317
Property Name Vacuum Grayburg San Andres Unit	Well No 018

Surface Location

UT. - Lat K	Section 1	Township 18S	Range 34E	Feet from 1330	N/S Line S	Feet From 1330	E/W Line W	County Lea
----------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ SWD	PRODUCER OIL GAS	DATE 4-4-19
--	--	--	---------------------	----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1810
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 ☒ X
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR ☒
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS ☒
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	If applicable type
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	fluid injected for
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

~~Plugged~~

Not Plugged

RIR

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness:	