

District 1

1625 N. French Dr. Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-35562
Property Name Vacuum Grayburg San Andres Unit		Well No. 235

7. Surface Location

UT. - Lat	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
H	1	18S	34E	2610	N	660	E	Lea

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	☒ SWD ☐	OIL ☐ GAS ☐	4-4-19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	0	N/A	N/A	0	1759
Flow Characteristics					
Puff	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	CO2 _____
Steady Flow	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	WTR _____
Surges	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	GAS _____
Down to nothing	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	If applicable type
Gas or Oil	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	fluid injected for
Water	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Nad rtk for Prod. CSS. (fluid)
Bleed down

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			