

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-38785
Property Name Vacuum Grayburg San Andres Unit		Well No. 438

2. Surface Location

U/L - Lot A	Section 1	Township 18 S	Range 34 E	Feet from 10	N/S Line N	Feet from 420	E/W Line E	County Lea
----------------	--------------	------------------	---------------	-----------------	---------------	------------------	---------------	---------------


Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR (INJ)	PRODUCER OIL	DATE 4-4-19
------------------	----------------	-------------------	-----------------	----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E) Tubing
Pressure	0	0	NA	0	1808
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness: 