

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 29 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-02227	
Property Name Vacuum Grayburg San Andres Unit		Well No 064	

Surface Location

1/4 - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
M	35	17S	34E	660	S	660	W	Lea



Well Status

T&D Well		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	(OH)	GAS	4/13/19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	30	400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type _____
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for _____
Water	Y/N	Y/N	Y/N	Y/N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness:		