

HOBBS OCD

APR 29 2019

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-27976
Property Name Vacuum Grayburg San Andres Unit	Well No 067

Surface Location								
1/4 - Lot L	Section 35	Township 17S	Range 34E	Feet from 2630	N/S Line S	Feet from 120	E/W Line W	County Lea

Well Status					DATE
TA'D Well YES	SHUT-IN NO	INJECTOR NO	PRODUCER OIL	GAS	4/14/19

OBSERVED DATA

	(A)Surf-Interm	(B)Internl(1)	(C)Internl(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	0	1-8
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Shut in due to Broken Valve stem

Signature: <i>Chris Jones</i>	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	12/2
Phone:	
Witness:	