HOBBS OCD

MAY 01 2019

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cross Timber Energy, LLC						^{3.} API Number 3002524027		
Property Name North Vacuum ABO East Unit						Well No. 5		
				^{7.} Surface Location				
UL - Lot B	Section 18	Township 17S	Range 35E	Feet from 660	N/S Line FNL	Feet From 1980	E/W Line FEL	County Lea
				Well Status			•	

Well Status	SHUT-IN	PRODUCING	DATE	
	NO		4-9-2019	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	\mathcal{D}		·······	0	4150
Flow Characteristics	~~~~				1
Puff	Y / 🕅	Y / N	Y / N	Y / 🔕	1
Steady Flow	Y / Ø	Y / N	Y / N	Y/O	1
Surges	Y/O	Y / N	Y / N	Y/O	1
Down to nothing	Y / Ø	Y/N	¥ / N	Y/O	
Gas or Oil	Y / Ø	Y/N	Y / N	Y/O	1
Water	Y / M)	Y / N	Y/N	Y / ()	1

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK	
lemarks:			INJECTING AT THIS TIME	WTR. GAS.	<u>C02</u>
marks:			INJECTING AT THIS TIME	WIR, UA3,	02

Signature: Jou lavas	OIL CONSERVATION DIVISION			
Printed name: Jose CASAS	Entered into RBDMS			
	Re-test	VW		
Tille: /PASE OperAtor E-mail Address: TLASAS OCT Fields UCS. Com		10		
Date: 4-9-2015 Phone: 575-746,7220				
Witness:				