District | 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

MAY 01 2019

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT

State of New Mexico

RECEIVED

Operator Name Cross Timber Energy, LLC Property Name North Vacuum ABO East Unit								³ API Number 3002529383 Well No.			
L			NO		rface Locatio					12	
UL · Lot Section Township Range Feet from N/S Line								Feet From	E/W Line	County	
E 18		17S	17S 35E		2000	FN	FNL 66		FWL	Lea	
Well Status											
Well	Status		SHUT-IN		PRODUCDIG		4-9-2015				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUA											
OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:											
			Surf-Interm	(B)Interm(1)-Interm(2)	(C)Int	(C)Interm-Prod		D)Prod Csng	(E)Tubing	
Pressure			D				··· ·· ·-		35	20	
Flow Characteristics											
Puff			x 109	Y /	Y / N		Y / N		YIV]	
Steady Flow		1	v / 🚱	Y/N		Y / N			YIN		
Surges		1	Y /(N)	Y / N			Y / N		Y / N		
Down to no		. L	(/ ()	Y / N		Y / N			Y / N		
	Gas or Oil		(/ (S)	Y /		Y/N			Y / N	1	
Water	Water		Y / Ø	¥ /	N	Y/N			Y / N	J	
If bradenhead	flowed wat	ter, check al	of the descriptio	ns that apply:							
CLEAR	CLEAR		FRESH SALTY		ГҮ	SULFUR		R	BLACK		
										<u></u>	
Remarks:						INJECTIN	√G AT T	THIS TIME	(GAS,CO2	
Signature: Jose Casas Printed name: Jose Casas Title: lease Operator E-mail Address: Tlasas O et Fields vis lon								OIL CONSERVATION DIVISION Entered into RBDMS Re-test			
Date: 4-9-2019 Phone: 575: 746-7220											