<u>District_I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

MAY 01 2019

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT

RECEIVED

	Operator N Cross Timber I		³ API Number 3002529384								
Property Name North Vacuum ABO East Unit								Well No. 13			
				^{7.} Su	rface Locatio	n					
UL - Lot Section Township M 18 17S		Range 35E		Feet from 509	N/S Line FSL	Feet From 684		E/W Line FWL	County Lea		
				V	Well Status						
Well Status			SHUT-IN	_		4	4-9-2016		}		
If bradenhead			HEAD AND INTE	OBSI	O ATMOSPHER ERVED DA	RE INDIVIDUALL T A	Y FOR 15 MII	NUTES I	EACH		
			Surf-Interm		1)-Interm(2)	(C)Interm-Pro	o <u>d</u>	(D)Prod Csng		(E)Tubing	
Pressure			0					30		25	
Flow Characteristics											
Puff				Y /	' N	Y / N		Y / N		1	
Steady Flow			(1 1	Υ /	N	Y / N		Y / N]	
Surges		ſ	(100)	Υ /	N	Y / N		Y / N			
Down to nothing			(1 6)	Υ /	N	Y / N		Y / N			
Gas or Oil			(/ (N)	Υ /	N	Y / N		Y / N			
Water			(/ (R)	Υ /	N	Y / N		Y / N			
<u>If bradenhead</u>	flowed wa	ter, check all	of the descriptio	ns that apply:							
CLEAR		FRE	SH SALT		TY	SULFUR		BLACK			
Remarks:						INJECTING AT	THIS TIME _	w	TR,	GAS,CO2	
Signature: Jou long Printed name: Dose CASAS Title: //ASL Operator							OIL CONSERVATION DIVISION Entered into RBDMS Re-test				
E-mail Addre			ctFields	ves. lon	7223					<u> </u>	
Date: 4-	Date: 4-9-2019 Phone: 575-746-7220									· · · · · · · · · · · · · · · · · · ·	
Witness:											