

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

MAY 01 2019

RECEIVED

Operator Name Cross Timber Energy, LLC	API Number 3002529389
Property Name North Vacuum ABO East Unit	Well No. 18

7. Surface Location

UL - Lot K	Section 18	Township 17S	Range 35E		Feet from 1870	N/S Line FSL	Feet From 2065	E/W Line FWL	County Lea
---------------	---------------	-----------------	--------------	--	-------------------	-----------------	-------------------	-----------------	---------------

Well Status

Well Status	SHUT-IN NO	PRODUCING ✓	DATE 4-9-2019
-------------	---------------	----------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	D			35	20
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: <i>Jose Casas</i>	OIL CONSERVATION DIVISION
Printed name: Jose Casas	Entered into RBDMS
Title: <i>Leak Operator</i>	Re-test
E-mail Address: <i>JCasas@ctfields.com</i>	
Date: 4-9-2019	
Phone: 575-746-7220	
Witness:	