

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-06868
Property Name Central Drinkard Unit	Well No. #123

1. Surface Location

UL - Lot M	Section 28	Township 21S	Range 37E	Feet from 1660	N/S Line FSL	Feet From 1660	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status Active	SHUT-IN YES	PRODUCING Injecting	DATE 4-19-2019
------------------------------	-----------------------	-------------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Shut in at the moment.
diverting water.

Signature: Emanuel Jimenez	OIL CONSERVATION DIVISION
Printed name: Emanuel Jimenez	Entered into RBDMS
Title: S.S.P.S.	Re-test
E-mail Address: ETC1@Chevron.com	
Date: 4-19-2019	
Phone: 575-631-9139	
Witness:	