

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-06917
Property Name Central Drinkard Unit	Well No. #151

7. Surface Location

UL - Lot 1	Section 32	Township 21S	Range 37E	Feet from 1980	N/S Line FSL	Feet From 330	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status Active	SHUT-IN yes	PRODUCING Injecting	DATE 4-19-2019
------------------------------	-----------------------	-------------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	☒	☒	N/A	☒	☒
Flow Characteristics					
Puff	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	
Steady Flow	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	
Surges	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	
Down to nothing	☒ Y/N	☒ Y/N	Y/N	☒ Y/N	
Gas or Oil	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	
Water	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ☒	FRESH ☒	SALTY ☒	SULFUR ☒	BLACK ☒
---	---	---	--	---

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Shut in diverting water

Signature: Emanuel Jimenez	OIL CONSERVATION DIVISION
Printed name: Emanuel Jimenez	Entered into RBDMS
Title: S.S.P.S.	Re-test 7/7
E-mail Address: EJ@Chevron.com	
Date: 4-19-2019	
Phone: 575-631-9139	
Witness:	