

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SEELY OIL CO		API Number 30-025-37572-0000
Property Name EK PENROSE SAND UNIT		Well No. 701

7. Surface Location

UL - Lot D	Section 30	Township 18-S	Range 34-E	Feet from 740	N/S Line N	Feet From 330	E/W Line W	County LEA
----------------------	----------------------	-------------------------	----------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 5/1/19
-------------------------	-----------------------	------------------------	------------------------	-----------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	0
Flow Characteristics					Not INS
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(David) maccliskey ser # 0733 cal 1-14-19
Post Workover Test
Start 380#

Signature:		OIL CONSERVATION DIVISION	
Printed name: Mike Frazier		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: nitromikey@mywdo.com			
Date: 5/1/19	Phone: 575-390-2171		
Witness: KERRY FORTNER- OCD 575-399-3221			

