

District I1625 N French Dr. Hobbs, NM 88249
Phone (575) 393-6161 Fax (575) 393-0729State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office**BRADENHEAD TEST REPORT**

Operator Name Chevron Midcontinent, LP	API Number 30-025-02248
Property Name Vacuum Grayburg San Andres Unit	Well No 042

7. Surface Location

UL - Lot G	Section 1	Township 18 S	Range 34 E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line E	County Lea
---------------	--------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 4/14/19
--	--	---	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		120	380
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	CO2 _____
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	WTR _____
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	GAS _____
Down to nothing	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	If applicable type _____
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	Fluid injected for _____
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test 
E-mail Address.	
Date:	
Phone	
Witness.	