

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-24364
Property Name Vacuum Grayburg San Andres Unit		Well No 046

Surface Location

U.L. - Lot H	Section 2	Township 18 S	Range 34 E	Feet from 1405	N/S Line N	Feet From 1230	E/W Line E	County Lea
-----------------	--------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS	DATE 4-4-19
--	--	--	---	----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Casing
Pressure	0	1405 0	1405	0	1755
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 ☒
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR ☒
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS ☒
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	If applicable type
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	fluid injected for
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test 	
E-mail Address:			
Date:	Phone		
	Witness 