

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-26281
Property Name Vacuum Grayburg San Andres Unit		Well No 059

Surface Location									
U.I. - Lot E	Section 2	Township 12 S	Range 34 E		Feet from 2500	N/S Line N	Feet From 40	E/W Line W	County Lea

Well Status						DATE
TA'D Well YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ NO	PRODUCER OIL	GAS
						9/14/95

OBSERVED DATA

	(A)Surf-Intern	(B)Intern(1)	(C)Intern(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	0	2017
Flow Characteristics					
Puff	☒ Y	☒ Y	☒ Y	☒ Y	CO2
Steady Flow	☒ Y	☒ Y	☒ Y	☒ Y	WTR ☒
Surges	☒ Y	☒ Y	☒ Y	☒ Y	GAS
Down to nothing	☒ Y	☒ Y	☒ Y	☒ Y	If applicable type
Gas or Oil	☒ Y	☒ Y	☒ Y	☒ Y	fluid injected for
Water	☒ Y	☒ Y	☒ Y	☒ Y	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Chris (A) [Signature]</i>		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test <i>RR</i>
E-mail Address:		
Date:	Phone:	
Witness:		