

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-24332
Property Name Vacuum Grayburg San Andres Unit		Well No. 004

1. Surface Location

UL - Lot M	Section 1	Township 18S	Range 34E	Feet from 220	N/S Line S	Feet From 100	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ SWD	PRODUCER OIL GAS	DATE 4-4-19
--	--	--	---------------------	----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A		1831
Flow Characteristics					
Puff	☒	☒	☒	☒	CO2 _____
Steady Flow	☒	☒	☒	☒	WTR _____
Surges	☒	☒	☒	☒	GAS _____
Down to nothing	☒	☒	☒	☒	If applicable type
Gas or Oil	☒	☒	☒	☒	fluid injected for
Water	☒	☒	☒	☒	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

~~Fail~~ Bled prod. csg. down, fluid would not stop - closed valve
 30 sec. built up little pres + pushed more water out.
 closed valve + built up to 60 PSI Again.

Fail BHT

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION
Printed name: _____		Entered into RBDMS <i>[Signature]</i>
Title: _____		Re-test
E-mail Address: _____		
Date: _____	Phone: _____	
Witness: <i>[Signature]</i>		