

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-03108
Property Name Hobbs N State		Well No. 001

1. Surface Location

1/4 - Lot D	Section 8	Township 18 S	Range 35 E	Feet from 330	N/S Line N	Feet from 358	E/W Line W	County Lea
----------------	--------------	------------------	---------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR INJ ☐ SWD ☐	PRODUCER ☒ OIL ☐ GAS	DATE 4/14/19
--	--	---	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Surface
Pressure	0	NA	NA	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>B.R.</i>		OIL CONSERVATION DIVISION
Printed name		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
	Witness	