State of New Mexico

Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

		Texlan	Operator l		ENHEAD TE s, LLC	ST RE	O C	NT O	N. W.	30-025-377	1 46	
Property Name White							<u> </u>			Well No. #01		
·					7. Surface Locati	ion		0=		<u> </u>	<u> </u>	
UL - Lot Section To		Township	Township Range		Feet from		, , , , , , , , , , , , , , , , , , , 		rom	E/W Line	County	
I	30	16S	38E		1886'	So	uth	51	1'	East	Lea	
					Well Status	1						
Well	Status		SHUT-IN		PRODUCING WIW		5-8-1		9			
	OPE	N BRADENI	HEAD AND INT	ERMEDIA'	TE TO ATMOSPHE	RE INDIV			MINUT	ES EACH		
					OBSERVED DA	TA						
If bradenhead	l flowed wa		of the description		_	1 (CN) A			4888	10		
h		(A)Su	(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure Flow Characteristics			U						$\downarrow U$		540	
Puff			¥ / 🚱		Y/N		Y/N		Y/199		-	
Steady Flow			¥/6		Y / N		Y/N		Y / Ø		-	
Surges			Y/(N)		Y/N		Y/N		Y / 6		-	
Down to nothing			Ø/N		Y/N		Y / N		ØY N		-	
Gas or Oil			Y / 9		Y / N		Y/N		Y/Q		[
Water		Y / 🛭		Y / N		Y/N		·	Y/N		j	
If bradenbead	l flowed wa	ter, check all	of the description	ns that anni	v:							
CLEAR			FRESH		SALTY		SULFUR		BLACK			
Remarks:	•									•••		
										· ···		
							ir	<u> </u>				
Signature:								OIL CONSERVATION DIVISION				
Printed name:								Entered into RBDMS				
Title:								Re-test				
E-mail Addr	ess: v smi	th@texpet	ro.com								Pι	
Date:			Phone: 575-433-8395							· · ·		
			W. Manas Guatas alch									