

District I
1625 N. French Dr., Hobbs, NM 88241
Phone: (575) 393-6161

HOBBS OCD

MAY 24 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Pogo Oil + Gas Operating		*API Number 30-025-01448	
Property Name Caprock Maljamar Unit		Well No. 31	

Surface Location									
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
0	17	17S	33E	660	S	1980	E	LEA	

Well Status									
TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE					
YES <input type="radio"/>	YES <input type="radio"/>	INJ <input checked="" type="radio"/>	OIL <input type="radio"/> GAS <input type="radio"/>	5-20-2019					

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	2400
Flow Characteristics					CO2 <input type="checkbox"/> WTR <input checked="" type="checkbox"/> GAS <input type="checkbox"/> Type of Fluid Injected for Waterflood if applies
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	<input checked="" type="radio"/> Y/N	Y/N	Y/N	<input checked="" type="radio"/> Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: apollo.salas44@gmail.com	
Date: 5-23-2019	Phone: 575-492-1236
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM