

HOBBS OCD

MAY 24 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Pogo Oil + Gas Operating		*API Number 30-025-01455	
Property Name Caprock Maljamar Unit		Well No. 019	

Surface Location									
UL - Lot L	Section 17	Township 17S	Range 33E		Feet from 1980	N/S Line S	Feet From 660	E/W Line W	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INI	SWD	PRODUCER OIL	GAS	DATE 5-20-2019	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			10	1300
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 — WTR X GAS —
Steady Flow	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Had some fluid but bled down

Signature: <i>Dillon Salas</i>		OIL CONSERVATION DIVISION	
Printed name: Dillon Salas		Entered into RBDMS	
Title: Production Engineer		Re-test	
E-mail Address: apollo.salas44@gmail.com			
Date: 5-23-2019	Phone: 575-492-1236		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM