

District 1
1625 N. Hobbs Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0729

HOBBS OCD
MA 24 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Pago Oil & Gas Operating						API Number 30-025-11310			
Property Name Langlic Jal Unit						Well No. 9			
Surface Location									
UL - Lat F	Section 32	Township 24S	Range 37E		Feet from 1980	NS Line N	Feet From 1980	E/W Line W	County LEA
Well Status									
TA'D WELL YES ☒ NO ☐		SHUT-IN YES ☐ NO ☒		INJECTOR YES ☐ NO ☒		PRODUCER YES ☒ NO ☐		DATE 5-17-2019	

OBSERVED DATA

	(A) Surface	(B) Intermed 1	(C) Intermed 2	(D) Prod Csg	(E) Tubing
Pressure	30			0	590
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐ WTR ☒ GAS ☐ Type of fluid injected for waterflood if applicable
Steady flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Bleed Down in 1 minute

Signature: Dillon Salas		OIL CONSERVATION DIVISION	
Printed name: Dillon Salas		Entered into RBDMS	
Title: Production Engineer		Re-test	
E-mail Address: apollo.salas44@gmail.com			
Date: 5-23-2019	Phone: 575-492-1236		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM