

HOBBS OCD

MAY 20 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-03109	
Property Name Hobbs N State		Well No 002	

Surface Location

UL - Lot C	Section 8	Township 18S	Range 35E	Feet from 330	N/S Line N	Feet From 1650	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

PROD Well ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR INJ ☐ SWD ☐	PRODUCER ☒ OIL ☐ GAS	DATE 4/14/19
--	--	---	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	40	0
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	PO2 _____
Steady Flow	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	WTR _____
Surges	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	GAS _____
Down to nothing	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	If applicable type _____
Gas or Oil	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	Fluid injected for _____
Water	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	☒ Y ☐ N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>B. K.</i>		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test <i>[Signature]</i>	
E-mail Address:			
Date:	Phone:		
	Witness:		