

District I
1625 N. French Dr.
Phone: (575) 390-6100 Fax: (575) 390-6101

HOBBS OCD
RECEIVED
MAY 24 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Pago Oil & Gas Operating		*API Number 30-025-12041	
Property Name South Leonard Unit		Well No. 6	

Surface Location									
UL - Lot H	Section 23	Township 26S	Range 37E		Feet from 1980	N/S Line N	Feet from 660	E/W Line E	County LEA

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJECTOR NO	SWD	PRODUCER OIL	GAS	DATE 5-17-2019	

OBSERVED DATA

	(A) Surface	(B) Latecom(1)	(C) Intermed(2)	(D) Prod Case	(E) Tubing
Pressure	0			0	25
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR X GAS Type of Fluid Indicated for Waterflood if applies.
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	0 N	Y/N	Y/N	0 N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillon Salas		OIL CONSERVATION DIVISION	
Printed name: Dillon Salas		Entered into RBDMS	
Title: Production Engineer		Re-test	
E-mail Address: apollo.salas44@gmail.com			
Date: 5-23-2019	Phone: 575-492-1236		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM