

HOBBS OCD
 District
 1625 N. French Dr. Hobbs, NM 88340
 Phone: (575) 393-1111 Fax: (575) 393-0771
RECEIVED
 MAR 24 2019

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Prigo Oil & Gas Operating</i>		API Number <i>30-025-09063</i>	
Property Name <i>Seven Rivers Queen Unit</i>		Well No. <i>11</i>	
Surface Location			
UL - Lot <i>K</i>	Section <i>27</i>	Township <i>22S</i>	Range <i>36E</i>
Feet from <i>1980</i>		N/S Line <i>S</i>	Feet from <i>1980</i>
E/W Line <i>W</i>		County <i>LEA</i>	
Well Status			
TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐
			DATE <i>5-17-2019</i>

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure	<i>0</i>			<i>0</i>	<i>0</i>
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐ WTR ☒ GAS ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Dillon Salas</i>		OIL CONSERVATION DIVISION
Printed name: Dillon Salas		Entered into RBDMS
Title: Production Engineer		Re-test <i>[Signature]</i>
E-mail Address: apollo.salas44@gmail.com		
Date: 5-23-2019	Phone: 575-492-1236	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM